20 OCt 2014 , HY475653

Becvar, Lance J.

Sent: Friday, July 17, 2015 12:33 PM
To: Lewin, Jonathan H.
Cc: Dziak, Steven E.

Hello Dep Lewin,
Per your request the findings related to the Aggravavted Assault / Police involved Shooting on 20 Oct 2014 Listed under RD# HY 475653:

Findings from thart night-

Veh 8779   Video Recovered Titled PC0Z400@20141020215250, No MICs because they were in the Glove Compartment with the batteries inserted unside down - Disabling them.

Veh 8489   System not engaged because a very long video (like hours long) was made previous to this event/incident and the system was processing that video and unable to start another video.

Veh 8765   System not engaged, officer related no power. There was no open HDT called in on vehicle. MICs not sync'd to system even though they were in the charging cradles.

Veh 6412   Video Recovered Titled PC0S571@20141020215250 view out of focus. Foucsing problem found to be related to a loose cable connection for the camera. No MICs in vehicle and the charging cradles disconnected from power.

Veh 8949   System not engaged, officer reported that there was an application error - Mobile Recorder Start-Up corrupted. No Help Desk Ticket Open for this vehicle.

Sgt Lance Becvar

MobileTech Supervisor

Information Services Division

Chicago Police Department
Cell# 312-446-3305
E-mail: lance.becvar@chicagopolice.org